

Chemistry Microbiology, and Technical Services

CLIENT: Alaskan Copper Works

P. O. Box 3546 Seattle, WA 98124

ATTN : Dale Olsen

Work ID

: Discharge Water

Taken By

: Client

Transported by: -

Type

: Water

SAMPLE IDENTIFICATION:

Sample

Description Metro Waste Discharge

Date 05/14/90

Collection

Unless otherwise instructed all samples will be discarded on 07/16/90

Respectfully submitted, Laucks Testing Laboratories, Inc.

Certificate of Analysis

Work Order# : 90-05-236

DATE RECEIVED : 05/15/90 DATE OF REPORT: 05/23/90

CLIENT JOB ID : M14964

MAY 25 1990



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.



Chemistry Microbiology, and Technical Services

CLIENT : Alaskan Copper Works

Certificate of Analysis

Work Order # 90-05-236

TESTS PERFORMED AND RESULTS:

Analyte	Units	<u>01</u>
Chromium (Method 218.1)	mg/L	0.30
Copper (Method 220.1)	mg/L	0.078
Nickel (Method 249.1)	mg/L	0.17
Zinc (Method 289.1)	mg/L	0.019



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.

MAY 25 1990